

---

## FIRMWARE REVISION HISTORY

- 151.000 First production release of firmware  
All features made standard except PF regulation  
Check exciter field disabled while starting  
Off settings added to exciter/field voltage, current and resistance elements.
- 152.000 Display now refreshed every 30s.
- 200.000 Modbus communications added  
Off settings for protection elements standardized
- 201.000 FAR relay not always being released upon motor stopping error corrected
- 202.000 Removed runtime fault error on starts when measured locked rotor current exceeds programmed locked rotor current.  
Improved communications intergrated.